





ABSTRACT

A vending machine provides a warning indication that insufficient change may be available if the total amount of available change is less than the value of the highest-denomination monetary unit which is not refundable. An insufficient change indication is also provided in response to inserting a coin or instructing a vending operation which would result in the amount of refundable change being less than the correct amount by a value which is greater than a predetermined, alterable overpay amount.

10

5

FIG. 4